


Best Available Copy


Best Available Copy

FIG. 2

From Asian Cardiovasc Thorac Ann 1999;7:349-352



Best Available Copy







FIG. 5

METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

Neal L. Eigler et al.

Appl. No.: 10/628,880 Atty Docket: CEDAR.001A

Replacement Sheet
Reply to Office Action
of June 15, 2006



METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

Replacement Sheet
Reply to Office Action
of June 15, 2006

Neal L. Eigler et al.
Appl. No.: 10/628,880 Atty Docket: CEDAR.001A




FIG. 7

*Replacement Sheet
Reply to Office Action
of June 15, 2006*

Appl. No.: 10/628,880 Atty Docket: CEDAR.001A




FIG. 8

METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

Replacement Sheet
Reply to Office Action
of June 15, 2006

Neal L. Eigler et al.
Appl. No.: 10/628,880 Atty Docket: CEDAR.001A





FIG. 9

METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

Replacement Sheet
Reply to Office Action
of June 15, 2006

Neal L. Eigler et al.
Appl. No.: 10/628,880 Atty Docket: CEDAR.001A



METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

*Replacement Sheet
Reply to Office Action
of June 15, 2006*

Neal L. Eigler et al.

Appl. No.: 10/628,880 Atty Docket: CEDAR.001A




FIG. 11

METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

*Replacement Sheet
Reply to Office Action
of June 15, 2006*

Neal L. Eigler et al.

Appl. No.: 10/628,880 Atty Docket: CEDAR.001A






FIG. 12





METHODS AND APPARATUS FOR ATRIOVENTRICULAR VALVE REPAIR

Replacement Sheet
Reply to Office Action
of June 15, 2006

Neal L. Eigler et al.

Appl. No.: 10/628,880 Atty Docket: CEDAR.001A




FIG. 15

